## Oil Field Environmental Incident Summary

**Responsible Party:** SECURE ENERGY SERVICES USA, LLC **Well Operator:** SECURE ENERGY SERVICES USA, LLC

Well Name: WATFORD SWD 1

Field Name: PEMBROKE Well File #: 90166

Date Incident: 11/8/2015 Time Incident: 01:00 Facility ID Number:

County: MCKENZIE Twp: 149 Rng: 98 Sec: 6 Qtr: SW SW

Location Description:

Submitted By: John Freeman Received By:

Contact Person: John Freeman

555 17TH ST STE 800 DENVER, CO 80202-3908

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 20 Feet

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

	Spilled	Units	Recovered	Units
Oil	1	Barrels	1	Barrels
Rrine	5	Rarrols	5	Rarrole

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

**Risk Evaluation:**No immediate risk.

Areal Extent:

Followup Units

## Potential Environmental Impacts:

No immediate risk. Fluids contained

## Action Taken or Planned:

No environmental risk. Contained in tank farm. started cleaning up spill with Vac-truck and power washed exposed area.

Wastes Disposal Location: At our (Watford) SWD

Agencies Involved:

## **Updates**

Date: 11/10/2015 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release remained on location according to the report. NDIC retains oversight.